

GPOP - Issue Review System

Part Number: 04672585A\$

Part Description: Rear View Camera Module

Issue Description: Please review SOL S248A000008. A dealer may find vehicles equipped with RVC only, sales code XAC, may set U0565-00 erroneously in the radio. This fault code will not cause any operational issues. The rear camera is sending implausible data to the radio at times. If the technician is working on a vehicle with the above condition, a technician should not replace any parts if RVC is operating without any issues. Replacement cameras will set the same DTC without any operational complaints. Engineering is working on an update to improve the erroneous DTC from setting and the field will be notified upon completion.