

## Technical Service Bulletin (TSB)

### Fuel Tube Replacement

|                    |                                                                                                                                                                                                                                                   |       |              |                                                                                                                                                                                                                               |           |
|--------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| REFERENCE:         | TSB: 14-003-24<br>GROUP: 14 - Fuel System                                                                                                                                                                                                         | Date: | May 14, 2024 | REVISION:                                                                                                                                                                                                                     | 14-007-23 |
| VEHICLES AFFECTED: | 2023 (WL) Jeep Grand Cherokee<br>This bulletin applies to vehicles built on or before November 26, 2022 (MDH 1126XX) equipped with 3.6L V6 VVT Engine Upgrade 1 (Sales Code ERC).                                                                 |       |              | MARKET APPLICABILITY:<br><div><input checked="" type="checkbox"/> NA<input type="checkbox"/> MEA<br/><input type="checkbox"/> SA<input type="checkbox"/> IAP<br/><input type="checkbox"/> EE<input type="checkbox"/> CH</div> |           |
| CUSTOMER SYMPTOM:  | **Customers must experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find the following DTC has been set:** <ul style="list-style-type: none"><li>P0456 - EVAP System Small Leak.</li></ul> |       |              |                                                                                                                                                                                                                               |           |
| CAUSE:             | Fuel tank filler tube.                                                                                                                                                                                                                            |       |              |                                                                                                                                                                                                                               |           |

This bulletin supersedes Technical Service Bulletin (TSB) 14-007-23, date of issue August 11, 2023, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and includes removing a market, an updated RSU statement, an updated Customer Symptom statement and adding a NA RSU cancellation note.

**\*\*This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-238, date of issue August 11, 2023. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. \*\***

**NOTE: \*\*This proactive service action no longer in effect. Please follow published service procedures in Service Library to diagnose and repair the vehicle.\*\***

#### POLICY:

Information Only.