



Analysis Worksheet	
Topic	Airbag light on, B101C13, B101D13
Model(s) affected	2024 Q5, SQ5, Q5 Sportback, SQ5 Sportback
Documentation needed	- If the DTC B101C13 and/or DTC B101D13 is stored in the airbag control module, J234 (da0015), contact TAC. - Do NOT perform GFF or test plans for these DTCs. - Do Not perform any repairs or disconnect the affected seat belt buckle.
Questions	N/A
Other information: (Please include any other useful information from the customer or found during diagnosis.)	
 Note:	- Information requested in these worksheets update frequently. Please always use the latest worksheet on Elsa2Go. - Please include all information requested in the worksheet up front when submitting the WEB ticket to TAC.