

Audi On-car analysis list from June, 1 2024

Please contact Audi Helpline before attempting repair

As of 6/7/2024 worksheets will no longer be used as a standard practice. Worksheets will only be required if listed in the topic details.

	Models	MY	Engine	Trans	Topic	Topic details
	Q7, Q8	2017-2019	Any	Any	Corrosion on wheelhouse cover plate	2017-2019 Q7 2019 Q8 Various photos and inspections, see worksheet.
	Q5	2021-2024	Any	Any	Airbag light on, DTCs B101704, B103604	Do not perform GFF test plan Do not erase DTC See TSB 2073566 See worksheet for instructions
	Q5	2024	Any	Any	Q5 Airbag light	DTC B101C13, B101D13 Do not perform GFF test plan Do not erase DTC See worksheet for instructions
	Q4 e-tron	2022 - 2024	Any	Any	Roof panel buttons inop	Dome light buttons unresponsive or come on with no input Sunroof buttons are unresponsive (typically in addition to dome light) See worksheet for instructions
	Q7	2023-2024	Any	Any	Airbag light B12251B	If the DTC B12251B is stored in the airbag control module, J234 (da0015), contact TAC. Do Not perform GFF or test plans for this DTC. Do Not perform any repairs or disconnect the PODS sensor mat or PODS control module.
	Q5	2024	Any	Any	Front door(s) hard to close	Before making any repairs to the affected door, measure the dimensions of the door as outlined in the associated worksheet "Q5 Front door high closing effort."
	e-tron, Q8 e-tron	2023-2024	Any	Any	Water intrusion into cabin from kinked sunroof drain hose	Evidence of water intrusion from sunroof area e.g. dripping from the roof electronics module, water stains on headliner Kinked sunroof drain found Do not disturb the lines, contact TAC before repairs are made
	A4, S4, A4 allroad	2023-2024	Any	Any	the front windows is noisy and/or binding	- Before making any repairs to the affected window, take a video of the customer's complaint. - After identifying the root cause (e.g. window regulator, window guide, etc.) take a video of the causal part causing the customer's complaint. - If the complaint was resolved (e.g. by cleaning the slot seals or reinstalling the window guide) take another video of the window operation.
	Q7	2023-2024	Any	Any	Front door wind noise	Wind noise from front door while at highway speeds Details findings needed for source of noise See worksheet for further details