



Subject: MISSING DTCS FROM 2024 MX-5 WSM	Service Alert No.: SA-037/24
	Last Issued : 06/04/2024

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2024 MX-5

DESCRIPTION

The following DTCs are missing from the 2024 MX-5 WSM, but you can refer to the 2023 MX-5 for these DTCs to troubleshoot a 2024 model.

- B00A0:09
- B00A0:28
- B00A0:4A
- B00A0:54
- B00A0:55
- B00A0:81
- B00A0:87

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.