

Subject: Engineering Information - Check Engine Lamp Illuminated on Driver Information Center (DIC), DTC's P0202, P0203 Set

This EI have been revised to end the need for gathering information from the field. Please discard PIE0791A.

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	2023	2024	—	—	Equipped with 3.0L (RPO LM2)	—
Chevrolet	Silverado 1500					Equipped with 3.0L (RPO LZ0)	
	Suburban					Equipped with 3.0L (RPO LM2)	
	Tahoe					Equipped with 3.0L (RPO LZ0)	
GMC	Sierra 1500					Equipped with 3.0L (RPO LM2)	
	Yukon Models					Equipped with 3.0L (RPO LM2)	

If you encounter a vehicle with the above condition, both the injector and harness should be replaced.

Version	3
Modified	Released May 30, 2024 Revised June 05, 2024 - Updated Step 11 and added Email Address. Revised June 18, 2024 - Ended the need for gathering further information from the field.