



TECHNICAL SERVICE BULLETIN

Classification:

DA21-007B

Reference:

NTB21-106B

Date:

May 10, 2024

DTC C1A17-49 OR C2580-49 STORED IN LASER/RADAR

This bulletin has been amended. See AMENDMENT HISTORY on the last page.
Please discard previous versions of this bulletin.

APPLIED VEHICLES:

2019-2024 Altima (L34)
2017-2024 Armada (Y62)
2022-2024 Frontier (D41)
2018-2024 Kicks (P15)
2018-2024 LEAF (ZE1)
2016-2023 Maxima (A36)
2015-2024 Murano (Z52)
2016 Murano Hybrid (Z52H)
2014-2020 Rogue (T32)
2017-2019 Rogue Hybrid (T32H)
2017-2022 Rogue Sport (J11)
2020-2024 Sentra (B18)
2016-2024 Titan/Titan XD (A61)
2020-2024 Versa (N18)

SERVICE INFORMATION

If DTC C1A17-49 for "CONTROL UNIT" / "ICC SENSOR" / "ICC SENSOR MALF" or C2580-49 for "CONTROL UNIT" is stored in LASER/RADAR in the "PAST" column:

- Erase the DTC.
- DO NOT replace any parts.

If DTC C1A17-49 or C2580-49 is stored in LASER/RADAR in the "CURRENT" column, refer to the applicable ESM for instructions.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 15, 2021	NTB21-106	Original bulletin published
March 9, 2023	NTB21-106A	APPLIED VEHICLES revised and DTC descriptions added
May 10, 2024	NTB21-106B	APPLIED VEHICLES revised

