

9100409

09/06/2024

MY 25, 21-24, 19-24 DT 22-24, 23-25 WS

GPOP - Issue Review System

Part Number: 05038870A\$, 68250776A\$, 68415458A\$, 68415459A\$, 68415460A\$,
68492340A\$, 68535805A\$, 68535806A\$, 68535807A\$, 68535808A\$,
68584764A\$

Part Description: TRANSFER CASE

Issue Description: Before replacing a transfer case unit for fault codes C1444-98 and/or C1477-4B, be sure to reference TSB 21-048-24 for potential transfer case shift motor replacement.