



Bulletin No.: PIC6500B
Published date: 08/2/2024

Preliminary Information

PIC6500B Super Cruise Unavailable Message - Has Ended

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Cadillac LYRIQ		2023	All	All All	All

Involved Region or Country	North America
Additional Options (RPO)	UKL - Super Cruise
Condition	Customers may notice a Super Cruise Unavailable, Adaptive Cruise Unavailable or a Service Driver’s Assist message on the DIC. Technician may find the following DTC's setting in the Image Processing Module, see chart below.
Cause	Engineering investigation has ended.

Correction:

If any of these DTCs in the table below set refer to normal SI diagnostics.

DTC #
B1DD0 sym49
B1DD0 sym57
B1DD0 sym38
U023B sym00
U023C sym00
U053C sym00
U1624 sym00
U1962s ym00
U3006 sym16
U1615 sym00
U1616 sym00
U3000 sym49

U0140 sym00
U3000 symF0
U1617 sym00
U0131 sym00
U0411 sym00
U053B sym00

Version History

Version3	
Modified	04/03/2023 - Created. 05/24/2023 - Updated to include additional DTC's 08/02/2024 - Updated to end PI and refer to SI.