


RAPID UPDATE

FROM: Maserati TSO

TO: Maserati Network



PERSONAL SERVICE LAB

MASTERS OF CARE

Rapid Update 743 Grecale - AGSM Software Update



DATE: September 4, 2024

Certain Maserati Grecale (M182) MY23 MY24 and MY25 listed in MODISCS+ are involved in a Rapid Update to update the AGSM (Automatic Gearbox Shifter Module) software.

This action is necessary to prevent the Park button from potentially getting "stuck ON" or the inability to shift the gear out of "P." This issue could prevent the vehicle from being moved and may result in DTCs P07BE-00/1E1700 being stored in the AGSM.

We remind you that all the Rapid Updates must be performed within the first workshop visit, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

Please read and review this bulletin first before ordering parts and/or starting the procedure.

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions.

Thank You for your continued support and cooperation.

Maserati North America
Aftersales Dept.

Technical Procedure



All images shown in this bulletin are for illustrative purposes only

1. Always check ModisCS+ to see if the vehicle is involved in this action and if it has not been previously performed.
2. Before proceeding, please ensure that the Engine is OFF.
3. Connect a battery maintainer to the 12V battery (It is recommended to always use the E-XTEQ MAXIMUS to maintain minimum voltage and current draw requirements)
4. Connect the EVO to the vehicle, ensure that battery voltage is around 12.5V then select **AGSM ► ECU Programming** and follow the prompts.

Software version to be installed (or newer).

Market	F188
ROW	670353212

ROW = Rest Of World

5. After the update has successfully completed. Clear any residual DTC's.
6. Procedure complete.

Warranty Claim

Fill in the Warranty Claims as follows:

Description	Code
Rapid Update Number	743
Warranty Code	23
Fault Code	063
Component Code	3.02.037
Operation Code	3.02.037.A (0,20h)