

9100412

09/16/2024

MY 24-25 JL

GPOP - Issue Review System

Part Number: 68593176\$\$

Part Description: P2 TO PIM harness

Issue For fault B273C-00 - Before replacing P2 to PIM HV Harness - REFER TO SOL
Description: S2408000063