



SSM 53061 2021-2024 F-150, 2023-2024 F-Super Duty - Air Conditioning (A/C) Inoperative - DTC P2CFC

Some 2021-2024 F-150 and 2023-2024 F-Super Duty vehicles may exhibit an inoperative A/C system that only blows warm air with diagnostic trouble code (DTC) P2CFC stored in the body control module C (BCMC). Pinpoint Test C in Workshop Manual (WSM), Section 412-00 has been updated to improve diagnostics for this DTC. Voltage remaining on the A/C clutch field coil circuit when uncommanded does not require replacement of the BCMC.