



Bulletin No.: PIP6002A
Published date: 09/20/2024

Preliminary Information

PIP6002A 10L80 MHT MI2 MQB No Reverse No Shift Past Third Gear P2732

Models

Brand: Model: Model Years:			VIN: from to		Engine: Transmissions:
Chevrolet Camaro	2024		ALL	ALL ALL	MI2
Chevrolet Silverado	2024		ALL	ALL L84	MHT MQB
GMC	Sierra	2024	ALL	ALL L84	MHT MQB

Involved Country/Region:	North America, North Africa, Philippines, Asia/Pacific, Europe, International Fleet Sales, Middle East operations, South America,
Concern:	No Reverse, Transmission Will Not Shift Past 3 rd Gear and/or DTC P2732.
Cause:	Internal valve body issue

Correction:

Replace The Valve Body Assembly. - Please refer to the Electronic Parts Catalog for the latest PN.

Version History

Version	2
Modified	08/30/2024 - Created on. 09/20/2024 - Added RPOs and updated Models.