

Audi On-car analysis list from September, 10 2024**Please contact Audi Helpline before attempting repair****As of 6/7/2024 worksheets will no longer be used as a standard practice. Worksheets will only be required if listed in the topic details.**

	Models	MY	Engine	Trans	Topic	Topic details
	A4, A5, Q5	2023-2024	Any	Any	Gas cap seal deformed (P045600)	DTC P045600 (very small Leak) Leak Detected) is present. Check gas cap to see if seal is deformed <u>Open a TAC case and provide the requested information.</u>
	A5 Q5	2023-2024 2023-2024	DPAA DPVA	any	02 Sensor P013B00	Before performing work on the vehicle proceed as follows: 1. Verify DTC P013B00 (Sensor Bank1-Sensor2 Slow Response – Lean to Rich) 2. Contact TAC for further instruction. Possible onsite.
	A3, Q3	2024	Any	Any	MIB3 – Stuck on loading user information when booting up	If the following criteria is met, contact TAC for possible data logger installation: - On bootup, the screen is stuck at the "loading user information" screen - User interaction is not possible during this time - Backup camera works normally
	Q4 e-tron	2022 - 2024	Any	Any	Roof panel buttons inop	Dome light buttons unresponsive or come on with no input Sunroof buttons are unresponsive (typically in addition to dome light) <u>See worksheet for instructions</u>