

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title Not possible to erase DTC U114C51		Ref. No. TJ 37099.1.0	
Issuer (Dept.) Technical Service		Issue Date 10/3/24	Status Date 10/14/24
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3610	
Function Description Programming and diagnosis		Page Page 1 of 1	

DESCRIPTION:

In cases where DTC U114C51 (Production SW Download Signature Public Key. System Programming Failures. Not programmed.) is set after a replacement of a module and this DTC cannot be erased, follow the advice under service.

CSC Customer Symptom Codes

Code	Description
3L	Technician information/Repair information/Not for warranty use
2V	Technician information/Software/Vehicle communication/Not for warranty use

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
AUD	U114C51	Permanent
CCM	U114C51	Permanent
CEM	U114C51	Permanent
EGSM	U114C51	Permanent
SAS	U114C51	Permanent
VCU1	U114C51	Permanent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
416							2024-9999		0000001-0999999	202337-999952

SERVICE:

Start by reading this journal prior to any VIDA fault tracing.

This is a ghost DTC and can be ignored. It will cause no issue with the operation of the vehicle, and it will not hinder the vehicle from receiving an OTA (Over the Air Update).

Warranty claim info:

No warranty claim is accepted for this TJ.

VEHICLE REPORT:

No Vehicle Reports are required for this DTC.