



Technical Service Bulletin

27 e-tron GT 12V battery discharged - P1D6C00

27 24 82 2075846/1 October 31, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2022 - 2024	All	Not Applicable

Condition

Customer states:

- Electrical system fault lamp lights up.
- Vehicle does not start.

Workshop findings:

The following DTC and symptom code is logged in the Data Bus On Board Diagnostic Interface -J533- (address word 0019):

- DTC P1D6C00:** 12V battery faulty - **Symptom:** 8519692 – Active/static OR Passive/sporadic.

Technical Background 1

Check 12V battery due to DTC entry.

Production Solution

No production change.

Service

The following DTC and symptom code is logged in the Data Bus On Board Diagnostic Interface -J533- (address word 0019):

- DTC P1D6C00:** 12V battery faulty - **Symptom:** 8519692 – Active/static OR Passive/sporadic



Technical Service Bulletin

Run the associated test log in Guided Fault Finding for DTC P1D6C00:

Adhere to Guided Fault Finding

Replacing the battery without an instruction to do so from Guided Fault Finding is not permitted.



Try to reproduce the customer complaint (based on the description/cause of the issue), so that it can be clearly assigned to this TSB. The following repair must only be carried out if all the criteria (model/type, chassis number, engine/motor and gearbox code, PR number(s), part number, software version, code etc.) apply exactly. Otherwise, this solution will not eliminate the concern, and repeat repairs may be necessary. In such a case, we may reject the warranty claim and charge back the cost of the parts.

Warranty

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2706		
Damage Code:	0040		
Labor Operations:	GFF / Guided Functions	0150 0010	See SRT with associated operations
	GFF / Guided Functions	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2075846/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (**2075846**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.