



Technical Service Bulletin

96 Camera for Driver Assist Systems: DTC B2F0100, B200FF0 stored

96 24 08 2075994/1 November 15, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q4 e-tron, and Q4 Sportback e-tron	2022 – 2025	All	Not Applicable

Condition

Customer states:

- The driver assist systems are sporadically unavailable or there is a message displayed on the instrument cluster:
- Adaptive cruise assist not working.
- Lane assist: currently unavailable. See owner's manual.
- Audi pre sense: currently restricted. See owner's manual.
- Audi pre sense not working.
- After a few moments or after switching the ignition off and back on again, the instrument cluster messages disappear and the systems are available again.

Workshop findings:

The following DTCs and symptom codes are stored **sporadically** in the Camera for Driver Assist Systems -R242-, (address word 00A5):

- **DTC B200FF0:** Internal malfunction (symptom number: **1124116**).

and/or

- **DTC B2F0100:** Development code 1 (symptom number: **1124198**).



NOTICE

This TSB only applies if at least one of the event memory entries above is logged.

Technical Background 1

Highly sporadic system-related "resets" within the image processing cause the driver assist systems to stop working for a short period.



Technical Service Bulletin

Production Solution

None, this behavior is considered normal.

Service

- Instruct the customer that this condition is normal.
- Do not perform any repairs. Any repairs for this concern may be denied.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

CAUTION

There is no reason to replace parts or attempt repairs. Any labor/replacement parts invoiced without approval will be charged back. Invoicing under warranty is not permitted.

Additional Information

All part and service references provided in this TSB (**2075994**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.