



Bulletin No.: PIT6267
Published date: 10/28/2024

Preliminary Information

PIT6267 History DTC U0422 Set In The K5 Automatic Air Leveling Control Module Should Be Ignored

Models

Brand:	Model:	Model Years:	VIN: from to		Engine:	Transmissions:
Chevrolet Suburban		2025	All	All	All	All
Chevrolet Tahoe		2025	All	All	All	All
GMC	Yukon Models	2025	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	F47
Condition	It maybe found that when checking the vehicle for DTCs a History U0422 is set in the K5 Automatic Level Control Module.
Cause	Software anomaly.

Correction:

If the K5 Automatic Air Level Control Module has a history DTC U0422 it should be cleared and ignored.

NOTE: This does not cause any customer complaints, warning messages or warning indicators.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8086058*	Ignore and Clear History DTC U0422 From The K5 Automatic Level Control Module	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	10/28/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.