

SSM 53233 2025 F-650/F-750 - 6.7L - Illuminated MIL With DTC P20A5 - Built On Or Before 10-Oct-2024

Some 2025 F-650/F-750 vehicles equipped with a 6.7L and built on or before 10-Oct-2024 may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P20A5 stored in the powertrain control module (PCM). This DTC does not affect vehicle durability, and no additional diagnosis or service is required for this condition at this time. Inform customers that they can continue to drive the vehicle, and engineering is currently working on a solution for this condition that is expected in Q1 2025. Monitor PTS for additional information and schedule service appointments for customers once the repair becomes available.