



STAR ONLINE PUBLICATION



Case Number: S2408000130

Release Date: December 2024

Symptom/Vehicle Issue: Changing Tires to a Larger Size Triggers a Park Assist Module (PAM/PTS) to Set Diagnostic Trouble Code (DTC) B222A Vehicle Line Mismatch

Technician Observation: The technician finds when installing oversized aftermarket tires the PAM/PTS module sets the above DTC.

Discussion: The parktronics module software has compatibility limits for max tire size of 33.5. Tires installed that are above this max setting will trigger the B222A DTC. Engineering is aware of the concern and investigating a possible solution.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found