



**Bulletin No.:** PIT6314  
**Published date:** 01/9/2025

## Preliminary Information

### PIT6314 DTC U1615 Lost Communication With Image Processing Module 1 - Processor 1 On CAN Bus 2

#### Models

|               |               |                     |                        |                |                       |
|---------------|---------------|---------------------|------------------------|----------------|-----------------------|
| <b>Brand:</b> | <b>Model:</b> | <b>Model Years:</b> | <b>VIN:</b><br>from to | <b>Engine:</b> | <b>Transmissions:</b> |
| Chevrolet     | Silverado EV  | LT 2025             | All                    | All            | All                   |

|                            |                                                                                                         |
|----------------------------|---------------------------------------------------------------------------------------------------------|
| Involved Region or Country | North America                                                                                           |
| Additional Options (RPO)   | -UKL                                                                                                    |
| Condition                  | During a DTC pull a Technician may notice a Current DTC:U1615 set in the BCM that can't not be cleared. |
| Cause                      | Software Anomaly for trucks built without Supercruise.                                                  |

#### Correction:

Engineering is aware of the issue and this PI will be updated when a fix becomes available. Technicians are instructed to ignore this DTC when performing vehicle diagnostics.

#### Version History

|          |                          |
|----------|--------------------------|
| Version  | 1                        |
| Modified | 01/09/2025 - Created on. |



GM Global Brands  
© 2025 General Motors. All Rights Reserved.