

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title Check engine light and DTC - ECM P061C48/P060C48		Ref. No. TJ 36920.1.0	
Issuer (Dept.) Technical Service		Issue Date 4/24/24	Status Date 5/2/24
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA, LLC	Function Group 2154	
Function Description Camshaft		Page Page 1 of 2	

DESCRIPTION:

If the customer experiences a Check Engine Light and/or message in DIM and one or both listed DTCs are set, please follow advice under "service".

DIM = Driver Information Module.

ECM = Engine Control Module

CSC Customer Symptom Codes

Code	Description
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
ECM	P061C48	Permanent
ECM	P060C48	Permanent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224	L1	BL1KERS					2022-9999		-	202122-999952
227	L1	BL1KERS					2023-9999		-	202222-999952
236	06	B06KERS					2022-9999		-	202122-999952
238	06	B06KERS					2022-9999		-	202122-999952
246	06	B06KERS					2022-9999		-	202122-999952
246	L1	BL1KERS					2022-9999		-	202122-999952
256	06	B06KERS					2023-9999		-	202222-999952
536	K9	BK9KERS					2023-9999		-	202220-999952
536	L1	BL1KERS					2023-9999		-	202222-999952

Technical Journal 36920.1.0

SERVICE:

1. Change engine oil and oil filter.
2. Reset DTCs.
3. Rev the engine at a standstill to 1500-2200 RPM, check if DTCs re-occur.

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Note that the TJ number must be stated in the repair order text.

NOTE: Your warranty claim will be rejected if the procedure in this TJ is not followed. This will be followed using warranty claim control.

VST Operation Number

VST Operation Number	Description
22207-2	Oil filter replace
36001-2	Diagnostic trouble codes read / reset / known Diagnostic trouble codes with VIDA
99922-2	General Reimbursement acc to TJ

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 2154.