

On-car analysis list from September 13th, 2019
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on 1429 and/or P0556	Customer states MIL-on (Must have P1429 and/or P0556 in the ECM and vacuum pump inoperative)
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P0133	Customer states MIL-on (Must have P0133 in the ECM)
	ATLAS	19	3.6 (CDVC)	All	MIL-on P0116	Customer states MIL-on (Must have P0116 in the ECM) (untouched vehicles)
	ATLAS	19	3.6 (CDVC)	All	Engine Oil Leak	Customer states engine oil leak (untouched vehicles)
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P00FE	Customer states MIL-on (Must have P00FE in the ECM)
Body	Jetta	19	All	All	Front Window Noise	Customer states front window(s) noisy during operation (untouched vehicles)
	Jetta, Tiguan	19	All	All	A/C Compressor Leak	A/C compressor leaking (untouched vehicles)
	Jetta	19	All	All	Door Module	Customer states "door warning light" on dash and/or locks, mirrors or window functions inoperative (untouched vehicles)