

On-car analysis list from October 14th, 2019
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P1429 and/or P0556	Customer states MIL-on (Must have P1429 and/or P0556 in the ECM and vacuum pump inoperative)
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P0133	Customer states MIL-on (Must have P0133 in the ECM) (untouched vehicles, REPEAT CASES ACCEPTED)
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P0496	Customer states MIL-on (Must have P0496 in the ECM)
	ATLAS	19	3.6 (CDVC)	All	MIL-on P0116	Customer states MIL-on (Must have P0116 in the ECM) (untouched vehicles)
Body	Jetta	19	All	All	Front Window Noise	Customer states front window(s) noisy during operation (untouched vehicles)
	Jetta, Tiguan	19	All	All	A/C Compressor Leak	A/C compressor leaking (untouched vehicles)
	ATLAS	18-19	All	All	Lift Gate Rust/Corrosion	Customer states the rear lift gate has rust or corrosion (untouched vehicles)
	Jetta	19	All	All	Door Module (water)	Customer states "door warning light" on dash and/or locks, mirrors or window functions inoperative (untouched vehicles)
Chassis	Jetta	19	All	All	Parking Brake Concerns	Customer states the parking brake will not disengage or parking brake error/warning light in MFI (Must have any of the following faults C100C01, C100C07, C100C29 in the ABS module)
Electrical	Jetta	19	All	All	Door Module	Customer states MIL-on (Must have U019900 and/or U020000 in the ECM)