

9003639

10/30/2016

MY16, 17

JK

GPOP - Issue Review System

Part Number: 04593949A\$, 04891731A\$

Part Description: Fuel Tank Pressure Sensor and Purge Valve Canister

Issue Description: Before replacing this part due to fault code P0441, please call David Thomas at cell (248) 613-6908. Engineering may want to visit dealers in the metro Detroit area with this condition. If you don't receive response within 15 minutes, please continue with normal repair procedure.~

~_____~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.