Technical Service Bulletin

01 MILon, DTC P164D(00) and/or Oil pressure warning on, V6 3.0TFSI

01 13 78 2033379/1 March 20, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, S4, S5, S5 Cabrio, Q7, Q5	2013	All	3.0 FSI Engine

Condition

- **DTC P164D00** (Oil pressure switch for reduced oil pressure malfunction) is stored in the engine control module, J623 (01).
- Red oil pressure warning light may be on.

Technical Background

An oil filter that is too short is installed. The oil filter must be 155 mm.

Production Solution

Improved oil filter.

Service

1. Check the length of the oil filter. It must be 155 mm long.
2. If the oil filter is faulty, too short, or too long, please contact Technical Assistance Center.

© 2013 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1730		
Damage Code:	0012		
Diagnostic Time:	Check oil filter	1730 1999	20 TU
	GFF – Checking and clearing fault codes	0150 0000	20 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2033379/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
06E115562A	Oil filter	1

© 2013 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.