



IC- Odometer Reading Blank & Maintenance Data Unavailable IC Box control unit name : IC223

Topic number	LI54.30-P-080963
Version	1
Function group	54.30 - Instrument cluster, display instruments, hazard warning device
Date	9/16/26
Validity	IC223
Reason for change	need to change remedy
Reason for block	RD no longer needs this further parts or logs for analysis

Complaint

Issue after OTA Update

IC Odometer Reading blank("_ _ _ _")

IC Maintenance data unavailable

Attachments

File	Description
DSCN0665[1] 1.JPG	
image (2).png	

Cause



OTA Update E61.0

Remedy

In the IC Control Unit Log, please check the following information:

Verify whether DTCs B228229, B228287, and B226656 are present in either A or A+S.

Verify that Status Schlüssel-ID = "ID is not valid" and Anlernstatus = "IC is initialized", as shown in the attached image (image_2).

Please run the XENTRY guided test for the listed DTCs and provide the results.

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it



imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms

Communication/information > Information display > Trip computer > Malfunction

Communication/information > Information display > Displays > Multifunction display > Function > Malfunction

Control unit/fault code

Control unit	Fault text
N133/1 - Instrument cluster (IC) / (IC223)	B228287 - The value of the main odometer reading is implausible. The message is missing.
N133/1 - Instrument cluster (IC) / (IC223)	B228229 - The value of the main odometer reading is implausible. There is an invalid signal.