GPOP - Issue Review System

Part Number: 68602151A$

Part Description: SENSOR Exhaust Temperature

Issue Description: If replacing this part due to an active or pending P242B fault code on a vehicle with low mileage (early-life condition), contact the STAR Center for guided diagnostics before clearing the fault code or replacing the part.